LATERITE

MATERIAL SAFETY DATA SHEET

THIS DOCUMENT REPRESENTS A MODIFICATION OF A U. S. DEPARTMENT OF LABOR OCCUPATIONAL SAFETY & HEALTH ADMINISTRATION NON-MANDATORY FORM

SECTION I - MANUFACTURER IDENTIFICATION

Manufacturer (Producer/Processor): IMCO Date: July 19, 2002

Address: 7268 Frasinetti Road

Sacramento, CA. 95828

Telephone: (916) 383-2811 FAX: (916) 383-8741

Product Name: LATERITE

SECTION II - HAZARDOUS INGREDIENTS/IDENTIFY INFORMATION

Component	Chemical Formula	Common Name	Threshold Limit Value Respirable Dust	%
Free Silica (Quartz)	SiO ₂	Silica	ACGIH: 0.1 mg/m ³	2+/-

Note:

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point (mm llg):	N/A	Specific Gravity (1120 = 1):	2.5
Vapor Pressure	N/A	Melting Point:	N/A
Vapor Density (Air = 1)	N/A	Evaporation Rate: (Butyl Aceiaic=1)	N/A
Solubility in Water:	N/A		

Appearance and Color: Reddish Tan - no odor

Laterite - continued 2 Page 2 of 2

SECTION IV - FIRE AND EXPLOSIVE HAZARD DATA

Flash Point:	Not Flammable	Flammable Limits:	Not Flammable
Extinguish Media:	N/A		
Special Fires Fighting Procedures:	N/A		
Unusual Fire and Explosion Hazards:	None		

SECTION V - REACTIVITY DATA

Stability:	Stable	Conditions to Avoid :	None
Incompatibility:	None	Material to Avoid:	None
Hazardous Decomposition or By products:	None		
Hazard Polymerization:	Will not Occur	Conditions to Avoid:	None

SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry:	Inhalation
	Health Hazards (Acute and Chronic):
Eye	May cause irritation.
Ingestion	N/A
Skin	May cause irritation.
Inhalation	Contains crystalline which may cause delayed respiratory disease (silicosis) if inhaled over a prolonged period of time. The State of California has determined crystalline silica to cause cancer.
Carcinogenicity:	IARC Monographs Volume 68, 1997 concludes that there is sufficient evidence that inhaling crystalline silica causes cancer in humans.
	Signs & Symptoms Exposure:
Medical Conditions	Respiratory system conditions.

Laterite - continued 3 Page 3 of 3

Aggravated (Exposure):		
Emergency & First Aid:		
Eye	Flush with plenty of water for 15 minutes, if irritation persists, see a physician.	
Ingestion	N/A	
Skin	Wash with mild soap and water.	
Inhalation	Remove to fresh air. If irritation persists see a doctor.	

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Material released or spilled:	Sweep up spill after wetting to avoid dust generation.
Waste disposal Method:	Dispose in closed containers at an approved landfill, in accordance with all federal, state and local laws
Precaution in Handling & Storing:	Keep in closed containers. Avoid creation of dust; use ventilation and exhaust equipment as required to abate dust in the work place.

SECTION VIII - CONTROL MEASURES

Respiratory Protection:	NIOSH approved dust mask (Wear 3M 7810 Dust Mask).
Ventilation:	Sufficient of maintain OSHA PEL.
Protection Gloves:	Appropriate to activity performed.
Eye Protection:	Recommended
Other Protective Clothing or Equipment:	Safety showers and eye washes.
Work/Hygienic Practices:	Brush clothing in natural ventilation; replace dust mask regularly. Good house keeping to minimize dust.

Laterite - continued 4 Page 4 of 4

(MSDS 12-99)